C.L. "BUTCH" OTTER - Governor RICHARD M, ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

July 9, 2007

Rose Murphy, Administrator Teton House 555 S 3rd West Rexburg, ID 83440

License #: RC-577

Dear Ms. Murphy:

On April 25, 2007, a Fire Life Safety Survey was conducted at Teton House. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted plan of correction and evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Safety, and Construction Program, at (208) 334-6626.

Sincerely,

Toph Bod

TAYLOR BARKLEY, Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/lj

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

FILE COPY



C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

June 6, 2007

Rose Murphy Residence Director Teton House 555 S. 5th W. Rexburg, Idaho 83440

FILE COPY

Dear Ms. Murphy,

I am in receipt of your request dated June 5, 2007 for a 30 day extension. This office is granting you the request of 30 days. This extension will expire on July 5, 2007.

Please keep me informed as to the progress and expected completion date for the project.

If you have any questions or concerns please feel free to contact me at (208) 334-6626.

Sincerely,

Taylor Barkley

Fire Life Safety and Construction Program

TB/tk



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T -- Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

May 2, 2007

Jennifer Davis, Administrator Teton House 555 S 3rd West Rexburg, ID 83440

Dear Ms. Davis:

On April 25, 2007, a life safety code survey was conducted at Teton House. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying evidence of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by May 25, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - ENTIRE BUILDING B. WING_ 13R577 04/25/2007 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **555 S 3RD WEST TETON HOUSE** REXBURG, ID 83440 (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on April 25, 2007. The surveyor conducting the survey was: **Taylor Barkley** Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899 OQVL21 If continuation sheet 1 of 1

TITLE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Tetan House	555 S. 3rd West	(208) 359-2478
Administrator	City	ZIP Code
Rose Murphy	Rexbur6 Id	83440
Survey Team Leader	Survey Type	Survey Date
Taylor Barkley		4: 25.7

NON-	-CORE ISSU	ES		
ITEM #	RULE# 16.03.22	DESCRIPTION	DATE RESOLVED	BFS USE
1	410.02	The facility does not have documentation for conducting the		
		required fire drills,		2 65 65
3:	405.05	The heat detector in the Cornace room of the Hitchen is		
<u> </u>		have no down by its wires. Fixed while on site	4-25.7	7/5
3,	405.05	The Kitchen has ovick response sprinkler heads mixed with		groups and
		Grdinary regionse heads		
4.	405.05	The following Areas and vooms have sprinkler heads that		30 (30 (3)) 27 (3) (4)
		have drapped down from the ceiling, leaving several opening	5	
		where the sprinkler head was originally installed. The	****	and the same of
		where the sprinkler head was originally installed. The rooms And Areas are as follows & Room # 125, Room # 127,		
		1200m # 126 in the closet, Room # 129, And Advapped head		
		in the corridor of front living area.		es autorial de la companya de la com
5,	405.05	The following rooms and areas have Quick response sprinkler		
		heads nixed with ordinary sprinkler heads, Room # 131 in		
		the closet, Room # 132, Room # 133 in the closet, Room # 135		
		in the claset, Room # 134 in the closet, And the maintenancer	oom,	
	se Required Date	Signature of Facility Representative And	Date Signed	[i]
	,		7 /	



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

Facility			Physical Address	Phone Number		
Teton House			555 S. 3rd West City Rexburg Id	(208) 359-247		
Administrator			City	ZIP Code		
Rose Murphy			Rexburg Id	83440		
Survey Team Leader			Survey Type	Survey Date		
Taylor Barkley				4-25-7		
NON	-CORE ISSU	ES '				
ITEM #	RULE# 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE
6.	405 05	The electrical room hi	As an opening in the wall Appr	av'matali		(S) 05 (G)
Year ,		one foot by five foot	A TOTAL DATE OF THE PARTY OF TH	OKIMA TRIY		55 55 55 5
<u>~~</u>	404.01	l , /				FT 65.65.0
7,	· I OF I · OF	The tacility does	not have Any emergency	Highting		
		IN three egress a	printors corrected on SITE - 17	2 2 M		
				ν		
					Waling	
						95) 65: 95: 0
				A		
			i e _{to}	· · · · · · · · · · · · · · · · · · ·		
•	se Required Date	Signature of Facility Representative			Date Signed	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
		The state of the s			<u> </u>	